

**Engr 210 – Lab #24**  
**Working Drawings and Assemblies**

For the given figure, do the following:

1. Create 3-D models for each part in SolidWorks.
2. Create dimensioned SolidWorks drawings of each nonstandard part.
3. Create an SolidWorks assembly of the parts.
4. Create a SolidWorks drawing of the assembly.

