


Engr 210 AA -- Engineering Graphics
Lab #8 - SECTIONAL VIEWS: Part 1

Instructions: Review the rules of sectioning (Chapter 8). For problem 2, you need to download the drawing file (Sectioning1.dwg) from the class website.

Problem 1: Given the front and top views, sketch full-section view for each object shown.



Problem 2: Download the drawing file (sectioning1.zip) from the class website.

Given in the figure labeled SECTIONING1 are the complete top and front views of a part to be machined from steel. Draw the right view with the aligned section A—A as indicated. Save the drawing file as **Lab8.dwg**.

